Announcing the release of Genesis Network Software Version 1.10.1

Release Category: Maintenance

Resolved Issues

- Need for manual reloading of the page after user is logged out due to inactivity.

- Alarms not clearing for non-Thermon controllers.

- Inability to rename the panel immediately after its addition to the network.

- Intermittent occurrence of errors while changing settings.

- Performance degradation for long duration on Alarms dashboard page.

- Bugs related to controller specific settings for some of the non-Thermon controllers as well as legacy Thermon controllers.

- Alarm acknowledgement issues for steam panels.

- Inability to download network configuration files.

- Inability to download the alarms report file.

- Cosmetic changes for display of temperature graphs.

- Alignment of the time axis on the history graphs.

Thermon software download portal: https://www.thermon.com/software-download/

Rohit Jain

Senior Product Manager – Controls & Monitoring