

## Genesis Network Software Version 1.10 (Release Notes)

Release Category: **Minor**

### Key Features

- Enhanced support for Genesis Duo
- Support for steam panels

### Resolved Issues

- Database performance issue with long-running queries.
- Automatic data refresh issue on the UI upon receipt of new data.
- Fix to the Genesis Bridge firmware to resolve the issue of not being able to perform firmware updates on any of the Genesis controllers in presence of a TC1818a in that Genesis bridge network.
- Resolution of alarms issues on the non-Thermon panels.

### Known Issues:

- **Progress Bar Stall:**  
At times, the progress bar may stall at less than 100% while pushing a firmware update to the network. It can occur if one or more bridges did not successfully receive the update.  
**Recommended Action:** In the network management tree, verify that the version tag next to each bridge shows the intended firmware update. If all bridges show updated with the correct version, the progress bar can be made to go away by clicking the “Stop Firmware Update” button.
- **Rendering**  
Gauges on the circuit view screen do not render at times.  
**Recommended Action:** Refresh the page.

Thermon software download portal: <https://www.thermon.com/software-download/>

Rohit Jain

Senior Product Manager – Controls & Monitoring