

Release Notes Genesis Panel Firmware v1.7.0

Release Category: **Minor**

Genesis Panel (v1.7.0)

Key Features

HMI

- Improved graph and history views.
- Implemented ability to quickly go right/left in time on a graph by holding down right/left buttons.
- Added graph legends to indicate type of reading/alarms.
- Added screensaver to reduce touch screen temperature during idle times.
- Implemented ability to adjust Ground Fault Alarm delay.

Resolved Issues

- Graph markers are now statically placed at the bottom instead of being dynamically placed.
- Addressed timestamp calculations used to query data for HMI graphs.
- Fixes related to min/max graph values, button combinations, time navigation on the graph, data validation, etc.
- Addressed issue related to transient noise values while the actual current reading is zero.
- Using Limiter control method now disables low temperature alarm and heater and ground fault current alarms for that circuit.
- Improved HMI performance on higher circuit could panels.

Note: This version of the Genesis Controller firmware must be used with TraceNet Sync v1.7.0. It is not compatible with the previous versions of TraceNet Sync.

Thermon highly recommends all our customers upgrade the Genesis panels in their network to the latest firmware version for enhanced experience. Please work directly with our field services or product management team to facilitate the upgrade.

Thermon software download portal: <https://www.thermon.com/software-download/>

In case of any issues, please report them at [Genesis Controller™ | Thermon](#) using the 'REPORT ISSUE' link on the page or send an email to ask.me@thermon.com.

Rohit Jain

Senior Product Manager – Controls & Monitoring